

S39392

36W/LED/HID/5000K/100-277V/E26 36 watt LED HID Replacement; 5000K; Medium base; 100-277 volts

Features

- High Lumen Omni-directional LED for Industrial / Commercial applications
- Replaces HID, CFL, and Incandescent
 Ballast by-pass Direct wire only 100V 277V
- UL approved for totally enclosed fixtures
 Damp location IP64 rated
- For outdoor & indoor use
- Base up, base down or horizontal operation
- Emits no UV light / Contains no mercury (Hg)
- 5 year limited warranty
- cÚLus listed

Additional Technical Specifications

- Power Factor >0.9
- Operating temperature range -20°C to 65°C
- Operating Frequency 50-60Hz
- Working Voltage AC90-305V
- Built in Surge Protection: 4KV

Shatter resistant materials, acceptable for use in food prep areas

Minimum Compartment Size							
Length	Width	Depth					
8.5 inch	6 inch	6 inch					

Optional Accessories

- In-line surge protector 80-929
- Mog to med socket reducer (rated up to 250V) 92-406



S39392

Item	Product	UPC	Input	Watts	Operating	Incandescent	Fluorescent
Number	Line	ne	Voltage		Frequency	Equivalent	Equivalent

S39392	Hi-Pro	04	5923303920) 100 - 27	7	36	50/60)Hz	200W			55W	
HID Equivale	ent Bas	e AN Ba		Lamp C	ode		D)immable/ Dimmat		-inish	MOL In Inches	-	
150W	Medi	um E2	26 36W/L	ED/HID/5000	K/100	-277V/E26	1	Non-Dimm	hable	White	7-11/32	2" 3-11/32"	
Initial Lumens	Average Ho	e Rated urs	Kelvin Temp	Color	CRI	Beam Spr Deg	ead	Burninç	9 Position	Ope	rating 1	Temperature	
5148	500	000	5000	Natural Light	80	300			[.] Down tion Only	-20C (·		a maximum of (+149F)	
Раск	ackage Type	CEC	Status	Material	C	RoHS Compliant	U	L or ETL Listed	UL Classification W		Warranty		
12	Box		for sale in ifornia	Aluminum		Yes		Yes	cULus - D F	amp Loo Rated	cation	5 Year Limited	



National Toll-Free: 800.43.SATCO (800.437.2826) www.satco.com Distribution Centers: New York, Florida, Texas, Washington, California, Puerto Rico Corporate Offices: 110 Heartland Blvd., Brentwood, NY 11717 800.437.2826 631.243.2022 Fax 631.243.2027



@2012, Satco Products, Inc. Not responsible for typographical errors. 06/12 S1051