



S9938

11.5T8/LED/48-830/DR-DM
 11.5 watt T8 LED; Medium bi-pin base; 3000K; 50000 average rated hours; 1700 lumens

Features

- Direct Replacement - for use on Instant Start and Rapid Start ballasts with no rewiring required*
- Solid State LED lighting
- Dimmable*
- Compatible with emergency ballasts*
- 25watt - 32watt Fluorescent equivalency
- DLC Listed
- NSF Approved
- 5 year Limited warranty

*May not be compatible with all rapid start, dimmable, and emergency ballasts. Ballast required

View:

- [Ballast Compatibility Chart](#)
- [Dimming Ballast Compatibility Chart](#)
- [Emergency Ballast Compatibility Chart](#)



S9938

| Item Number | UPC | Watts | Fluorescent Equivalent | Lamp Shape | Base | ANSI Base | Lamp Code | | |
|-----------------------------|--|-----------------|------------------------|---------------|---------------|----------------|-------------------------|-------------|--|
| S9938 | 045923099380 | 11.5 | 25W-32W | T8 | Medium Bi-Pin | G13 | 11.5T8/LED/48-830/DR-DM | | |
| Dimmable/Non-Dimmable | Suggested Dimmers | | Finish | MOL In Inches | MOD In Inches | Initial Lumens | Average Rated Hours | Kelvin Temp | |
| Dimmable* Ballast Dependent | Check Ballast MFG for Dimmer Compatibility | | White | 48" | 1.00" | 1700 | 50000 | 3000 | |
| Color | CRI | Beam Spread Deg | Pack | Package Type | CEC Status | DLC ID: | RoHS Compliant | | |

| | | | | | | | |
|------------------|----|-----------------------------|----|-------------------|--------------------------------|--|-----|
| Soft White | 82 | 220 | 10 | Eggcrate + Sleeve | Lawful for sale in California | PYJKYAXM DLC Search | Yes |
| UL or ETL Listed | | UL Classification | | | Warranty | | |
| Yes | | cULus - Damp Location Rated | | | 5 Year Limited | | |



National Toll-Free:
 800.43.SATCO
 (800.437.2826)
www.satco.com

Distribution Centers:
 New York, Florida, Texas,
 Washington, California,
 Puerto Rico

Corporate Offices:
 110 Heartland Blvd.,
 Brentwood, NY 11717
 800.437.2826 631.243.2022
 Fax 631.243.2027



©2012, Satco Products, Inc. Not responsible for typographical errors. 06/12 S1051